

PV Elite 2010 Error



Note: Error encountered while registering these dlls,

common_PV_08.dll, Shells_PV_08.dll, Wrc107_PV_08.dll, Nozzles_PV_08.dll, Conical_PV_08.dll, FloHead_PV_08.dll, Flanges_PV_08.dll, TemaTube_PV_08.dll, AsmeTube_PV_08.dll, HorizVes_PV_08.dll, RectVes_PV_08.dll, LegLug_PV_08.dll, PipePad_PV_08.dll, BaseRing_PV_08.dll, ThinJoint_PV_08.dll, ThickJoint_PV_08.dll, HalfPipe_PV_08.dll, LargeOp_PV_08.dll, Wrc297_PV_08.dll, AppendixY_PV_08.dll.

Run Netuser.bat file from the installation folder, otherwise Incorrect results may be produced !

You may need administrative rights to register the dlls. Contact your System Administrator.

OK